# YOUR ONESURVEY HOME REPORT

## **ADDRESS**

Birchwood Loch Flemington, Inverness IV2 7QR

## PREPARED FOR

Peter and Shona Peacock

**INSPECTION CARRIED OUT BY:** 

**SELLING AGENT:** 





HOME REPORT GENERATED BY:



## **Document Index**

Document	Status	Prepared By	Prepared On
Single Survey	Final	Inverness - Allied Surveyors Scotland Ltd	27/05/2025
Mortgage Certificate	Final	Inverness - Allied Surveyors Scotland Ltd	27/05/2025
Property Questionnaire	Final	Mr & Mrs. Peter and Shona Peacock	13/05/2025
EPC	FileUploaded	Inverness - Allied Surveyors Scotland Ltd	27/05/2025

## **Important Notice:**

This report has been prepared for the purposes and use of the person named on the report. In order to ensure that you have sight of a current and up to date copy of the Home Report it is **essential** that you log onto www.onesurvey.org (free of charge) to download a copy personalised in your own name. This enables both Onesurvey and the Surveyor to verify that you have indeed had sight of the appropriate copy of the Home Report prior to your purchasing decision. This personalised report can then be presented to your legal and financial advisers to aid in the completion of your transaction. **Failure to obtain a personalised copy may prevent the surveyor having any legal liability to you as they will be unable to determine that you have relied on this report prior to making an offer to purchase.** 

Neither the whole, nor any part of this report may be included in any published document, circular or statement, nor published in any way without the consent of Onesurvey Ltd. Only the appointed Chartered Surveyor can utilise the information contained herein for the purposes of providing a transcription report for mortgage/loan purposes.

PART 1

# SINGLE SURVEY

A report on the condition of the property, with categories being rated from 1 to 3.



# Single Survey

## Survey report on:

Surveyor Reference	I/25/05/076
Customer	Mr & Mrs. Peter and Shona Peacock
Selling address	Birchwood  Loch Flemington, Inverness
	IV2 7QR
Date of Inspection	23/05/2025
Prepared by	Keith Campbell, Assoc.RICS Inverness - Allied Surveyors Scotland Ltd

## SINGLE SURVEY TERMS AND CONDITIONS (WITH MVR)

#### **PART 1 - GENERAL**

### 1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property. <sup>1</sup>

If the Surveyors have had a previous business relationship within the past two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

 $\overline{\Omega}$ 

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

## 1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

<sup>&</sup>lt;sup>1</sup> Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Codes of Conduct

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

To date, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

### 1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller:
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

## 1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

## 1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained in the Report and the generic Mortgage Valuation Report. 2

## 1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

### 1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

### 1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for

expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

## 1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

### 1.10 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format.
- the "Market Value" is The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property.
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and

<sup>2</sup> Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Rules of Conduct.

- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

## **PART 2 - DESCRIPTION OF THE REPORT**

#### 2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

## 2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, *visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.* 

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

### 2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not

significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 2.3.1 <u>Category 3</u>: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2.3.2 <u>Category 2</u>: Repairs or replacement requiring future attention, but estimates are still advised.
- 2.3.3 Category 1: No immediate action or repair is needed.

**WARNING**: If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

## 2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

## 2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

## 2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

## 2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- \*There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- ➤ \*There are no particularly troublesome or unusual legal restrictions;
- \*There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property

## 1. INFORMATION AND SCOPE OF INSPECTION

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the Surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the Surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the Surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities will not be inspected or reported on.

Description	The subjects comprise an Architect designed detached 2 storey dwellinghouse.
Accommodation	The accommodation may be summarised as follows:-
	Ground Floor – Entrance Hall, Conservatory, Familyroom with Kitchen and Dining Area, Utility, Bedroom, Bathroom, WC compartment and Store.
	First Floor - Gallery Landing, Livingroom, Master Bedroom with Dressing Room and En-suite Bathroom, one further Bedroom with En-suite Showerroom and separate Study.
Gross internal floor area (m2)	Approximately 232 sqm.
Neighbourhood and location	The property forms part of an established rural residential nature, forming part of Loch Flemington which lies approximately 11 miles East of Inverness. There are limited local amenities in the immediate area but further amenities can be found in nearby Nairn or in Inverness.
Age	Built around 2004.
Weather	Weather conditions were dry, warm and bright at the time of inspection.
Chimney stacks	There is a single chimney stack constructed in concrete block with a rendered finish externally.  Visually inspected with the aid of binoculars where required.

	•
Roofing including roof space	The roof is of a traditional pitched design, clad externally with concrete interlocking tiles over timber trusses and plywood sarking material.
	Solar PV panels have been fitted.
	Internally, a ceiling hatch in the Landing provided access to the roof space and this found the area to be insulated with glass wool quilting.
	Sloping roofs were visually inspected with the aid of binoculars where required.
	Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property. If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so.
Rainwater fittings	The rainwater goods comprise PVC gutters and downpipes.
	Visually inspected with the aid of binoculars where required.
Main walls	The main outer walls comprise structural timber frame inner leaf and rendered concrete block outer leaf, plasterboard lined internally. There is a timber framed, timber clad stair feature at the Entrance Hall.
	Visually inspected with the aid of binoculars where required. Foundations and concealed parts were not exposed or inspected.
Windows, external doors	Windows throughout comprise timber framed double glazed units.
and joinery	The main entrance doors are timber framed.
	External fascias are formed in painted softwood and plywood.
	Internal and external doors were opened and closed where keys were available.
	Random windows were opened and closed where possible.
	Doors and windows were not forced open.
External decorations	As above, walls are rendered and timbers have a paint finish.
	Visually inspected.
Conservatories / porches	There is a Conservatory which is timber framed, double glazed and now has a pitched clad with a tile effect textured metal sheeting.
	Visually inspected.
Communal areas	None.
Garages and permanent outbuildings	There is an integral single car Garage which has an internal floor area extending to approximately 19 m2.
	Visually inspected.

The property benefits from garden grounds to the front, sides and rear which are mainty laid to a combination of gravelled driveway, grass, raised beds, pond, timber decking, vegetation and natural woodland. We are informed that the grounds extend to approximately 2 acres. Boundaries are formed in timber post and wire fencing.  Visually inspected.  Ceilings  Ceilings are plasterboard lined.  Visually inspected from floor level.  Internal walls  Internal walls and partitions are plasterboard lined.  Visually inspected from floor level.  Using a moisture meter, walls were randomly tested for dampness where considered appropriate.  Floors including sub floors  Flooring at ground floor level, is of a solid concrete design, whilst the upper floors are of a traditional suspended timber joist design. At the time of our inspection, the property was occupied, furnished and all floors had fitted coverings.  Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.  Internal joinery and kitchen remained in varnished hardwood finishes.  Internal doors comprise hardwood panelled units.  The Kitchen is fitted with wall and base units, together with associated worktops, stainless steel sink unit and integrated appliances.  The Utility is fitted with base units together with associated worktops and stainless steel sink unit and integrated appliances.  Kitchen units were visually inspected excluding appliances.  Chimney breasts and fireplaces  Visually inspected. No testing of the flues or fittings was carried out.  Internal decorations  Internally, walls and celling linings have a paint finish or are tile clad.  Visually inspected.	r	<b>,</b>
Ceilings   Ceilings are plasterboard lined.  Visually inspected from floor level.  Internal walls   Internal walls and partitions are plasterboard lined.  Visually inspected from floor level.  Using a moisture meter, walls were randomly tested for dampness where considered appropriate.  Floors including sub floors  Flooring at ground floor level, is of a solid concrete design, whilst the upper floors are of a traditional suspended timber joist design. At the time of our inspection, the property was occupied, furnished and all floors had fitted coverings.  Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.  Internal joinery and kitchen fittings  Internal doors comprise hardwood panelled units.  The Kitchen is fitted with wall and base units, together with associated worktops, stainless steel sink unit and integrated appliances.  The Utility is fitted with base units together with associated worktops and stainless steel sink unit.  Built-in cupboards were looked into but no stored items were moved.  Kitchen units were visually inspected excluding appliances.  Chimney breasts and fireplaces  There is a log burning stove fitted in the first floor Livingroom fireplace.  Visually inspected. No testing of the flues or fittings was carried out.  Internal decorations  Internally, walls and ceiling linings have a paint finish or are tile clad.  Visually inspected.		which are mainly laid to a combination of gravelled driveway, grass, raised beds, pond, timber decking, vegetation and natural woodland. We are informed that the grounds extend to approximately 2 acres.  Boundaries are formed in timber post and wire fencing.
Internal walls  Internal walls and partitions are plasterboard lined.  Visually inspected from floor level.  Using a moisture meter, walls were randomly tested for dampness where considered appropriate.  Floors including sub floors  Flooring at ground floor level, is of a solid concrete design, whilst the upper floors are of a traditional suspended timber joist design. At the time of our inspection, the property was occupied, furnished and all floors had fitted coverings.  Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.  Internal joinery and kitchen fittings  Internal joinery, notably that of skirtings and door surrounds, are formed in varnished hardwood finishes.  Internal doors comprise hardwood panelled units.  The Kitchen is fitted with wall and base units, together with associated worktops, stainless steel sink unit and integrated appliances.  The Utility is fitted with base units together with associated worktops and stainless steel sink unit.  Built-in cupboards were looked into but no stored items were moved.  Kitchen units were visually inspected excluding appliances.  Chimney breasts and fireplaces  There is a log burning stove fitted in the first floor Livingroom fireplace.  Visually inspected. No testing of the flues or fittings was carried out.  Internal decorations  Internal joinery, walls and ceiling linings have a paint finish or are tile clad.		Visually inspected.
Internal walls  Internal walls and partitions are plasterboard lined.  Visually inspected from floor level.  Using a moisture meter, walls were randomly tested for dampness where considered appropriate.  Flooring at ground floor level, is of a solid concrete design, whilst the upper floors are of a traditional suspended timber joist design. At the time of our inspection, the property was occupied, furnished and all floors had fitted coverings.  Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.  Internal joinery and kitchen fittings  Internal doors comprise hardwood finishes.  Internal doors comprise hardwood panelled units.  The Kitchen is fitted with wall and base units, together with associated worktops, stainless steel sink unit and integrated appliances.  The Utility is fitted with base units together with associated worktops and stainless steel sink unit.  Built-in cupboards were looked into but no stored items were moved.  Kitchen units were visually inspected excluding appliances.  Chimney breasts and fireplaces  There is a log burning stove fitted in the first floor Livingroom fireplace.  Visually inspected. No testing of the flues or fittings was carried out.  Internal decorations  Internally, walls and ceiling linings have a paint finish or are tile clad.  Visually inspected.	Ceilings	Ceilings are plasterboard lined.
Visually inspected from floor level.  Using a moisture meter, walls were randomly tested for dampness where considered appropriate.  Flooring at ground floor level, is of a solid concrete design, whilst the upper floors are of a traditional suspended timber joist design. At the time of our inspection, the property was occupied, furnished and all floors had fitted coverings.  Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.  Internal joinery and kitchen fittings  Internal joinery, notably that of skirtings and door surrounds, are formed in varnished hardwood finishes.  Internal doors comprise hardwood panelled units.  The Kitchen is fitted with wall and base units, together with associated worktops, stainless steel sink unit and integrated appliances.  The Utility is fitted with base units together with associated worktops and stainless steel sink unit.  Built-in cupboards were looked into but no stored items were moved.  Kitchen units were visually inspected excluding appliances.  Chimney breasts and fireplaces  There is a log burning stove fitted in the first floor Livingroom fireplace.  Visually inspected. No testing of the flues or fittings was carried out.  Internal decorations  Internally, walls and ceiling linings have a paint finish or are tile clad.  Visually inspected.		Visually inspected from floor level.
Using a moisture meter, walls were randomly tested for dampness where considered appropriate.  Flooring at ground floor level, is of a solid concrete design, whilst the upper floors are of a traditional suspended timber joist design. At the time of our inspection, the property was occupied, furnished and all floors had fitted coverings.  Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.  Internal joinery and kitchen fittings  Internal joinery, notably that of skirtings and door surrounds, are formed in varnished hardwood finishes.  Internal doors comprise hardwood panelled units.  The Kitchen is fitted with wall and base units, together with associated worktops, stainless steel sink unit and integrated appliances.  The Utility is fitted with base units together with associated worktops and stainless steel sink unit.  Built-in cupboards were looked into but no stored items were moved.  Kitchen units were visually inspected excluding appliances.  Chimney breasts and fireplaces  There is a log burning stove fitted in the first floor Livingroom fireplace.  Visually inspected. No testing of the flues or fittings was carried out.  Internal decorations  Internally, walls and ceiling linings have a paint finish or are tile clad.  Visually inspected.	Internal walls	Internal walls and partitions are plasterboard lined.
Floors including sub floors  Flooring at ground floor level, is of a solid concrete design, whilst the upper floors are of a traditional suspended timber joist design. At the time of our inspection, the property was occupied, furnished and all floors had fitted coverings.  Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.  Internal joinery and kitchen fittings  Internal joinery, notably that of skirtings and door surrounds, are formed in varnished hardwood finishes.  Internal doors comprise hardwood panelled units.  The Kitchen is fitted with wall and base units, together with associated worktops, stainless steel sink unit and integrated appliances.  The Utility is fitted with base units together with associated worktops and stainless steel sink unit.  Built-in cupboards were looked into but no stored items were moved.  Kitchen units were visually inspected excluding appliances.  Chimney breasts and fireplaces  There is a log burning stove fitted in the first floor Livingroom fireplace.  Visually inspected. No testing of the flues or fittings was carried out.  Internal decorations  Internally, walls and ceiling linings have a paint finish or are tile clad.  Visually inspected.		Visually inspected from floor level.
upper floors are of a traditional suspended timber joist design. At the time of our inspection, the property was occupied, furnished and all floors had fitted coverings.  Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.  Internal joinery and kitchen Internal joinery, notably that of skirtings and door surrounds, are formed in varnished hardwood finishes. Internal doors comprise hardwood panelled units.  The Kitchen is fitted with wall and base units, together with associated worktops, stainless steel sink unit and integrated appliances.  The Utility is fitted with base units together with associated worktops and stainless steel sink unit.  Built-in cupboards were looked into but no stored items were moved.  Kitchen units were visually inspected excluding appliances.  Chimney breasts and fireplaces  There is a log burning stove fitted in the first floor Livingroom fireplace.  Visually inspected. No testing of the flues or fittings was carried out.  Internal decorations  Internally, walls and ceiling linings have a paint finish or are tile clad.  Visually inspected.		
Internal joinery and kitchen fittings  Internal joinery, notably that of skirtings and door surrounds, are formed in varnished hardwood finishes.  Internal doors comprise hardwood panelled units.  The Kitchen is fitted with wall and base units, together with associated worktops, stainless steel sink unit and integrated appliances.  The Utility is fitted with base units together with associated worktops and stainless steel sink unit.  Built-in cupboards were looked into but no stored items were moved.  Kitchen units were visually inspected excluding appliances.  Chimney breasts and fireplaces  There is a log burning stove fitted in the first floor Livingroom fireplace.  Visually inspected. No testing of the flues or fittings was carried out.  Internally, walls and ceiling linings have a paint finish or are tile clad.  Visually inspected.	Floors including sub floors	upper floors are of a traditional suspended timber joist design. At the time of our inspection, the property was occupied, furnished and all floors had
fittings  varnished hardwood finishes.  Internal doors comprise hardwood panelled units.  The Kitchen is fitted with wall and base units, together with associated worktops, stainless steel sink unit and integrated appliances.  The Utility is fitted with base units together with associated worktops and stainless steel sink unit.  Built-in cupboards were looked into but no stored items were moved.  Kitchen units were visually inspected excluding appliances.  Chimney breasts and fireplaces  There is a log burning stove fitted in the first floor Livingroom fireplace.  Visually inspected. No testing of the flues or fittings was carried out.  Internal decorations  Internally, walls and ceiling linings have a paint finish or are tile clad.  Visually inspected.		· · · · · · · · · · · · · · · · · · ·
The Kitchen is fitted with wall and base units, together with associated worktops, stainless steel sink unit and integrated appliances.  The Utility is fitted with base units together with associated worktops and stainless steel sink unit.  Built-in cupboards were looked into but no stored items were moved.  Kitchen units were visually inspected excluding appliances.  Chimney breasts and fireplaces  There is a log burning stove fitted in the first floor Livingroom fireplace.  Visually inspected. No testing of the flues or fittings was carried out.  Internal decorations  Internally, walls and ceiling linings have a paint finish or are tile clad.  Visually inspected.		1
worktops, stainless steel sink unit and integrated appliances.  The Utility is fitted with base units together with associated worktops and stainless steel sink unit.  Built-in cupboards were looked into but no stored items were moved.  Kitchen units were visually inspected excluding appliances.  Chimney breasts and fireplaces  There is a log burning stove fitted in the first floor Livingroom fireplace.  Visually inspected. No testing of the flues or fittings was carried out.  Internal decorations  Internally, walls and ceiling linings have a paint finish or are tile clad.  Visually inspected.		Internal doors comprise hardwood panelled units.
stainless steel sink unit.  Built-in cupboards were looked into but no stored items were moved.  Kitchen units were visually inspected excluding appliances.  Chimney breasts and fireplaces  There is a log burning stove fitted in the first floor Livingroom fireplace.  Visually inspected. No testing of the flues or fittings was carried out.  Internal decorations  Internally, walls and ceiling linings have a paint finish or are tile clad.  Visually inspected.		<u> </u>
Chimney breasts and fireplaces  There is a log burning stove fitted in the first floor Livingroom fireplace.  Visually inspected. No testing of the flues or fittings was carried out.  Internal decorations  Internally, walls and ceiling linings have a paint finish or are tile clad.  Visually inspected.		
Chimney breasts and fireplaces  There is a log burning stove fitted in the first floor Livingroom fireplace.  Visually inspected. No testing of the flues or fittings was carried out.  Internal decorations  Internally, walls and ceiling linings have a paint finish or are tile clad.  Visually inspected.		· · · · · · · · · · · · · · · · · · ·
fireplaces  Visually inspected. No testing of the flues or fittings was carried out.  Internal decorations  Internally, walls and ceiling linings have a paint finish or are tile clad.  Visually inspected.		Kitchen units were visually inspected excluding appliances.
Internal decorations Internally, walls and ceiling linings have a paint finish or are tile clad.  Visually inspected.	•	There is a log burning stove fitted in the first floor Livingroom fireplace.
Visually inspected.	fireplaces	Visually inspected. No testing of the flues or fittings was carried out.
	Internal decorations	Internally, walls and ceiling linings have a paint finish or are tile clad.
Cellars None.		Visually inspected.
	Cellars	None.

Electricity	The property is connected to the mains electricity supply. The circuitry is protected by a consumer board which is wall mounted in the Hall cupboard.
	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances.
	Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the Surveyor will state that in the report and will not turn them on.
Gas	There is a sunken gas cylinder which supplies the Kitchen hob.
	Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances.
	Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the Surveyor will state that in the report and will not turn them on.
Water, plumbing and	The property is connected to the mains water supply.
bathroom fittings	Where visible, distribution pipework is formed in copper and soil/waste pipes are formed in PVC.
	The ground floor Bathroom is fitted with a 3 piece suite which includes WC, wash hand basin and bath with mixer shower over.
	The ground floor WC compartment is fitted with a 2 piece suite which includes WC and wash hand basin.
	The Master Bedroom En-suite is fitted with a 3 piece suite which includes WC, wash hand basin and bath with mixer shower over.
	The second first floor En-suite is fitted with a 3 piece suite which includes WC, wash hand basin and shower with mixer fitting.
	Externally, there is a tap fitted at the rear elevation.
	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.
	No tests whatsoever were carried out to the system or appliances.

Heating and hot water	Heating is by way of a ground source heat pump (NIBE F1145). This central heating system supplies a series of thermostatically controlled radiators at first floor level and underfloor heating at ground level.  Domestic hot water is via the central heating system and the pre-insulated hot water cylinder.  In addition to the central heating system, there is the log burning stove at first floor level.  Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.  No tests whatsoever were carried out to the system or appliances.
Drainage	Drainage is connected to a Klargester treatment plant.  Drainage covers etc were not lifted.  Neither drains nor drainage systems were tested.
Fire, smoke and burglar alarms	Smoke alarms are fitted in the property, together with a heat detector in the Kitchen and a carbon monoxide detector in the first floor Livingroom.  Visually inspected.  No test whatsoever were carried out to any systems or appliances.  There is now a requirement in place for compliant interlinked fire, smoke and heat detectors in residential properties. The new fire smoke and alarm standard came into force in Scotland in February 2022, requiring a smoke alarm to be installed in the room most frequently used for living purposes and in every circulation space on each floor. A heat alarm also requires to be installed in each kitchen. The alarms need to be ceiling mounted and interlinked. Where there is a carbon fuelled appliance such as a boiler, open fire or wood burner etc. a carbon monoxide detector is also required.  The surveyor will only comment on the presence of a smoke detector etc. but will not test them, ascertain if they are in working order, interlinked and / or fully compliant with the fire and smoke alarm standard that was introduced in 2022.  We have for the purposes of the report, assumed the system is fully compliant, if not then the appropriate compliant system will required to be installed prior to sale. This of course should be confirmed by your legal advisor.

## Any additional limits to inspection

Cupboards were all full of stored items thus limiting the inspection.

Furnishings restricted the inspection of internal walls and joinery.

There were floor coverings throughout which restricted the inspection of the flooring.

Stored items below the Kitchen sink blocked any view of the pipework.

We have not inspected the woodwork or other parts of the structure which were covered, unexposed or inaccessible and are, therefore, unable to report that such parts of the property are free from rot, beetle or other such defects.

No investigation of any contamination on, under or within the property has been made as we consider such matters to be outwith the scope of this report. All property built prior to the year 2000 may contain asbestos in one or more of its components or fittings. It is impossible to identify without a test. It is beyond the scope of this inspection to test for asbestos and future occupants should be advised that if they have any concerns, then they should ask for a specialist to undertake appropriate tests. Asbestos is not harmful unless fibres are released into the air.

Random testing for dampness was undertaken internally with the use of a moisture meter to walls, ceilings and flooring where considered appropriate.

The services, electrical circuits, plumbing installation, heating and drainage systems have not been specifically tested.

We do not carry out an inspection for Japanese Knotweed, which is a plant which is subject to control regulation, is considered to be invasive and one which can render a property unsuitable for some mortgage lenders. We have assumed that there is no Japanese Knotweed within the boundaries of the property or in neighbouring properties. Identification of Japanese Knotweed is best undertaken by a specialist contractor. If it exists, removal must be undertaken in a controlled manner by specialist contractors. This can prove to be expensive.

Normal maintenance is not treated as a repair for the purposes of the Single Survey. When a category 1 rating is provided this means the property must continue to be maintained in the normal way.

## Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

## 2. CONDITION

This section identifies problems and tells you about the urgency of any repairs by using one of the above 3 categories:

Category 3	Category 2	Category 1
	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Structural movemen	t
Repair category:	
Notes:	There was no indication of any structural movement affecting the property.

Dampness, rot and infestation	
Repair category:	
Notes:	There was no evidence of dampness, rot or infestations.

Chimney stacks	
Repair category:	
Notes:	No reportable defects.

Roofing including roof space	
Repair category:	
Notes:	No reportable defects.

Rainwater fittings	
Repair category:	
Notes:	No reportable defects.

Category 3	Category 2	Category 1
	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Main walls	
Repair category:	
Notes:	Generally, in satisfactory condition, although slight weathering was noted to the basecourse smooth render finish.
	Hairline cracking was noted at the rear Hall window, but this is not considered significant.

Windows, external doors and joinery	
Repair category:	1
Notes:	Generally, in satisfactory condition, although there is a failed sealed unit to one of the windows in the Conservatory which is being replaced prior to any sale.
	There would appear to be a failed sealed unit in the Velux window in the first floor Livingroom. This is to be replaced prior to a sale.

External decorations	
Repair category:	
Notes:	Externally, the property is found to be in a good decorative order.

Conservatories / porches	
Repair category:	
Notes:	The Conservatory roof has been replaced with a tile effect textured metal sheet finish, which has resulted in strengthening structural work.

Communal areas	
Repair category:	
Notes:	Not applicable.

Category 3		Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.		Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.
Garages and perm	anent outbuildings		
Repair category:	1		
Notes:	No reportable defects.		
Outside areas and	houndaries		
Repair category:	Doundaries		
Tropan category.	U		
Notes:	Garden grounds were found to be suitably tended around the property and the woodland area has been left in a natural state.		
Ceilings			
Repair category:	1		
Notes:	No reportable defects.		
Internal walls			
Repair category:	1		
Notes:	No reportable defects.		
Floors including au	h floors		
Floors including su Repair category:	1		
Notes:	No reportable defects.		
Internal joinery and	kitchen fittings		
Repair category:	- Interior intingo		

Notes:

No reportable defects.

Category 3	Category 2	Category 1
to other parts of the property or cause a safety	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Chimney breasts and fireplaces	
Repair category:	
Notes:	The fire was not in use at the time of inspection. The chimney flue should be checked and sept regularly in accordance with good practice.

Internal decorations	
Repair category:	
Notes:	Internally, the property is found to be in a good decorative order.

Cellars	
Repair category:	
Notes:	Not applicable.

Electricity		
Repair category:	2	
Notes:	It should be noted that only the most recently built or rewired properties will have installations which fully comply with present IET regulations. It is a recommendation that electrical installations be tested at least every 10 years, or upon a change of ownership. If the installation has not been tested within the last 10 years and a satisfactory Test Certificate obtained, then it is advised that an NICEIC qualified electrician undertake a full check of the installation prior to concluding Missives and any necessary upgrading works be undertaken in accordance with their recommendations.	

Gas	
Repair category:	
Notes:	Although not specifically tested, no visual defects are apparent.

Category 3	Category 2	Category 1
	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Water, plumbing and bathroom fittings			
Repair category:			
Notes:	Although not specifically tested, no visual defects are apparent.		

Heating and hot water		
Repair category:		
Notes:	Although not specifically tested, no visual defects are apparent.	

Drainage		
Repair category:		
Notes:	There was no indication of any surface issues.	

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the comments above for detailed information.

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	1
Roofing including roof space	1
Rainwater fittings	1
Main walls	1
Windows, external doors and joinery	1
External decorations	1
Conservatories / porches	1
Communal areas	
Garages and permanent outbuildings	1
Outside areas and boundaries	1
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	1
Internal decorations	1
Cellars	
Electricity	2
Gas	1
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

## Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

## Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

## 3. ACCESSIBILITY INFORMATION

**Guidance Notes on Accessibility Information** 

<u>Three steps or fewer to a main entrance door of the property:</u> In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

<u>Unrestricted parking within 25 metres:</u> For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coinoperated machines.

1. Which floor(s) is the living accommodation on?	Ground & First
2. Are there three steps or fewer to a main entrance door of the property?	[x]YES [ ]NO
3. Is there a lift to the main entrance door of the property?	[ ]YES [x]NO
4. Are all door openings greater than 750mm?	[x]YES [ ]NO
5. Is there a toilet on the same level as the living room and kitchen?	[x]YES [ ]NO
6. Is there a toilet on the same level as a bedroom?	[x]YES [ ]NO
7. Are all rooms on the same level with no internal steps or stairs?	[ ]YES [x]NO
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	[x]YES [ ]NO

## 4. VALUATION AND CONVEYANCER ISSUES

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated re-instatement cost for insurance purposes.

## Matters for a solicitor or licensed conveyancer

We have assumed that the property possesses a good and valid Title, and that the tenure is Standard or Absolute Ownership.

The full extent of the garden grounds should be confirmed via the Title Deeds.

Access to the property is over a shared driveway and we, therefore, assume that a formal right of access exists in favour of the subjects.

The private drainage system is assumed to be SEPA registered.

We understand that the solar PV panels are owned outright. Although we have not seen the terms of the Feed In tariff agreement, we understand that the property uses electricity made, with any balance sold to the National Grid.

## Estimated re-instatement cost (£) for insurance purposes

## 670,000

We are of the opinion that the subjects should be insured for buildings reinstatement purposes for a sum of not less than the above noted figure. Building costs are currently increasing significantly above inflation due to material and labour shortages as well as Brexit and the Pandemic. It is recommended that you update this figure regularly to ensure that you have adequate cover or alternatively seek specialist advice from your insurer.

## Valuation (£) and market comments

## 550,000

After full and careful consideration, we are of the opinion that the current open market value of the heritable subjects, as described, and with the benefit of full vacant possession can be fairly stated at a figure of Five Hundred and Fifty Thousand Pounds.

We have endeavoured to reflect market conditions currently prevailing in arriving at our opinion of value.

Report author:	Keith Campbell, Assoc.RICS		
Company name:	Inverness - Allied Surveyors Scotland Ltd		
Address:	Pavilion1 Fairways Business Park Inverness IV2 6AA		
Signed:	Electronically Signed: 287235-640524C0-094F		

# MORTGAGE VALUATION **REPORT**

Includes a market valuation of the property.





Mortgage Valuation Report				
Property:	Birchwood Loch Flemington, Inverness IV2 7QR		Client: Mr & Mrs. Peter and Shona Peacock Tenure: Scottish Ownership	
Date of Inspection:	23/05/2025	Reference:	KC/DEB/I/25/05/076	

This report has been prepared as part of the seller's instructions to carry out a Single Survey on the property referred to above. The purpose of this report is to summarise the Single Survey for the purpose of advising a potential lender on the suitability of the property for mortgage purposes. The decision as to whether mortgage finance will be provided is entirely a matter for the lender. You should not rely on this report in making your decision to purchase but consider all the documents provided in the Home Report. Your attention is drawn to the additional comments elsewhere within the report which set out the extent and limitations of the service provided. This report should be read in conjunction with the Single Survey Terms and Conditions (with MVR). In accordance with RICS Valuation – Global Standards 2017 this report is for the use of the party to whom it is addressed or their named client or their nominated lender. No responsibility is accepted to any third party for the whole or any part of the reports contents. Neither the whole or any part of this report may be included in any document, circular or statement without prior approval in writing from the surveyor.

### 1.0 LOCATION

The property forms part of an established rural residential nature, forming part of Loch Flemington which lies approximately 11 miles East of Inverness. There are limited local amenities in the immediate area but further amenities can be found in nearby Nairn or in Inverness.

2.0	DESCRIPTION	2.1 Age:	21 years.

The subjects comprise an Architect designed detached 2 storey dwellinghouse.

## 3.0 CONSTRUCTION

Walls - Cavity timber frame and rendered block construction, plasterboard lined internally.

Roof - Pitched and concrete tiled over timber trusses.

Floors - Solid concrete and suspended timber.

## 4.0 ACCOMMODATION

The accommodation may be summarised as follows:-

Ground Floor – Entrance Hall, Conservatory, Familyroom with Kitchen and Dining Area, Utility, Bedroom, Bathroom, WC compartment and Store.

First Floor - Gallery Landing, Livingroom, Master Bedroom with Dressing Room and En-suite Bathroom, one further Bedroom with En-suite Showerroom and separate Study.

5.0	SERVICES (	SERVICES (No tests have been applied to any of the services)					
Water:	Mains	Electricity: Mains Gas: LPG Drainage: Private					
Central Heating: Ground source heat pump.							
6.0	OUTBUILDINGS						
Garage: Integral single car Garage.							

Others:	None.					
7.0	GENERAL CONDITION - A building survey has not been carried out, nor has any inspection been made of any woodwork, services or other parts of the property which were covered, unexposed or inaccessible. The report cannot therefore confirm that such parts of the property are free from defect. Failure to rectify defects, particularly involving water penetration may result in further and more serious defects arising. Where defects exist and where remedial work is necessary, prospective purchasers are advised to seek accurate estimates and costings from appropriate Contractors or Specialists before proceeding with the purchase. Generally we will not test or report on boundary walls, fences, outbuildings, radon gas or site contamination.					
	s found to be in a good state	of repair and o	decoration, both internally ar	nd externally, ha	ving regard	
8.0	nstruction type.	V (as a conditi	on of any mortgage or, to pr	osonio the cond	dition of the	
	property)	.K (as a conditi	on or any mongage or, to pr	eserve the conc	intion of the	
None.	. vo o o momo o o do di	NEI				
	recommended:	Nil				
9.0	ROADS & FOOTPATHS otpath, but the road leading	to the property	is shared with neighbouring	properties		
10.0	BUILDINGS INSURANCE	670,000	GROSS EXTERNAL	Approximately	Square	
10.0	(£):	070,000	FLOOR AREA	255 sqm.	metres	
<b>11.0</b> We have assu	Ve have assumed that the property possesses a good and valid Title, and that the tenure is Standard or Absolute					
Access to the favour of the s The private dr We understan	rainage system is assumed to	veway and we be SEPA regi	, therefore, assume that a fo stered. ght. Although we have not se	en the terms of	the Feed In	
tariff agreeme Grid.	nt, we understand that the p	roperty uses el	ectricity made, with any bala	ince sold to the	National	
12.0	VALUATION On the assumption of vacant possession and that the property is unaffected by any adverse planning proposals, onerous burdens, title restrictions or servitude rights. It is assumed that all necessary Local Authority consents, which may have been required, have been sought and obtained. No investigation of any contamination on, under or within the property has been made as we consider such matters to be outwith the scope of this report. All property built prior to the year 2000 may contain asbestos in one or more of its components or fittings. It is impossible to identify without a test. It is beyond the scope of this inspection to test for asbestos and future occupants should be advised that if they have any concerns then they should ask for a specialist to undertake appropriate tests.					
12.1	Market Value in present condition (£):	550,000	(Five Hundred and Fifty The	ousand Pounds	)	
12.2	Market Value on completion of essential works (£):		N/A			
12.3	Suitable security for normal mortgage purposes?	Yes				

12.4	Date of Valu	ation:	23/05/2025			
Signature: Electronically		Signed: 2872	35-640524C0-094F			
Surveyor:	Keith Campb	ell	Assoc.RICS		Date:	27/05/2025
Inverness - A	Inverness - Allied Surveyors Scotland Ltd					
Office:	Pavilion1 Fairways Business Park Inverness IV2 6AA			Tel: 01463 239 494 Fax: email: inverness@allied	surveyorssc	otland.com

PART 3

# ENERGY REPORT

A report on the energy efficiency of the property.



# energy report

## energy report on:

Property address	Birchwood  Loch Flemington, Inverness  IV2 7QR
Customer	Mr & Mrs. Peter and Shona Peacock
Customer address	Birchwood  Loch Flemington, Inverness  IV2 7QR
Prepared by	Keith Campbell, Assoc.RICS Inverness - Allied Surveyors Scotland Ltd

## **Energy Performance Certificate (EPC)**

**Dwellings** 

## **Scotland**

## BIRCH WOOD, LOCH FLEMINGTON, INVERNESS, IV2 7QR

Dwelling type:Detached houseDate of assessment:23 May 2025Date of certificate:27 May 2025Total floor area:232 m²

**Primary Energy Indicator:** 73 kWh/m²/year

Reference number: 247
Type of assessment: Rd
Approved Organisation: Elm
Main heating and fuel: Gro

2471-1013-2205-9565-8200 RdSAP, existing dwelling

Elmhurst

Ground source heat pump,


radiators, electric

### You can use this document to:

- . Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO<sub>2</sub> emissions by improving your home

Estimated energy costs for your home for 3 years*	£6,030	See your recommendations
Over 3 years you could save*	£498	report for more information

<sup>\*</sup> based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




## **Energy Efficiency Rating**

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band B (86)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



## **Environmental Impact (CO<sub>2</sub>) Rating**

This graph shows the effect of your home on the environment in terms of carbon dioxide  $(CO_2)$  emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band B (88)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

## Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years
1 Low energy lighting	£80	£186.00
2 Solar water heating	£4,000 - £6,000	£312.00

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

## Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Timber frame, as built, insulated (assumed)	****	<b>★★★★</b> ☆
Roof	Pitched, insulated (assumed) Pitched, 300 mm loft insulation	**** ****	**** ****
Floor	Solid, insulated (assumed)	_	_
Windows	Fully double glazed	****	<b>★★★★</b> ☆
Main heating	Ground source heat pump, radiators, electric	****	****
Main heating controls	Time and temperature zone control	****	****
Secondary heating	Room heaters, wood logs	_	_
Hot water	From main system	***	****
Lighting	Low energy lighting in 56% of fixed outlets	****	****

## The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO<sub>2</sub> emissions, running costs and the savings possible from making improvements.

## The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 12 kg CO<sub>2</sub>/m<sup>2</sup>/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 2.9 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 0.4 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

## Estimated energy costs for this home

	Current energy costs	Potential energy costs	Potential future savings
Heating	£4,302 over 3 years	£4,341 over 3 years	
Hot water	£1,020 over 3 years	£702 over 3 years	You could
Lighting	£708 over 3 years	£489 over 3 years	save £498
1	Fotals £6,030	£5,532	over 3 years

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

## **Recommendations for improvement**

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

Da	and the second s	Indicative cost	Typical saving	Rating after improvement	
Re	ecommended measures	Indicative cost	per year	Energy	Environment
1	Low energy lighting for all fixed outlets	£80	£62	B 87	B 88
2	Solar water heating	£4,000 - £6,000	£104	B 88	B 90

## Choosing the right improvement package



For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to www.greenerscotland.org.

## About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

## 1 Low energy lighting

Replacement of traditional light bulbs with energy saving bulbs will reduce lighting costs over the lifetime of the bulb, and they last many times longer than ordinary light bulbs. Low energy lamps and fittings are now commonplace and readily available. Information on energy efficiency lighting can be found from a wide range of organisations, including the Energy Saving Trust (http://www.energysavingtrust.org.uk/home-energy-efficiency/lighting).

### 2 Solar water heating

A solar water heating panel, usually fixed to the roof, uses the sun to pre-heat the hot water supply. This can significantly reduce the demand on the heating system to provide hot water and hence save fuel and money. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. You could be eligible for Renewable Heat Incentive payments which could appreciably increase the savings beyond those shown on your EPC, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

## Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

## LZC energy sources present:

- Biomass secondary heating
- Ground source heat pump
- Solar photovoltaics

## Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit https://energysavingtrust.org.uk/energy-at-home for more information.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	25,435	N/A	N/A	N/A
Water heating (kWh per year)	2,795			

## **About this document**

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Mr. Keith Campbell

Assessor membership number: EES/010338

Company name/trading name: Allied Surveyors Scotland Ltd

Address: Lyle House, Pavilion 1 Fairways Business Park

Invernesshire Inverness IV2 6AA

Phone number: 01463 239 494

Email address: inverness@alliedsurveyorsscotland.com

Related party disclosure: No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

## Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

## Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit greeners cotland.org or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.

HOMEENERGYSCOTLAND.ORG
0808 808 2282
FUNDED BY THE SCOTTISH GOVERNMENT



# PROPERTY QUESTIONNAIRE

The owner of the property is required to complete this document which asks for information on the property such as 'Which council tax band?' etc.



Property Address	Birchwood
	Loch Flemington, Inverness
	IV2 7QR
Seller(s)	Peter and Shona Peacock
Completion date of property questionnaire	13/05/2025

Note for sellers

1.	Length of ownership					
	How long have you owned the property?					
	21 years					
2.	Council tax					
	Which Council Tax band is your property i	n? (Please circle)				
	[ ]A [ ]B [ ]C [ ]D [ ]E [ ]F [x]G [ ]H					
3.	Parking					
	What are the arrangements for parking at your property?					
	(Please tick all that apply)					
	Garage	[x]				
	Allocated parking space	[]				
	Driveway	[]				
	Shared parking	[]				
	On street	[]				
	Resident permit	[]				
	Metered parking	[]				
	Other (please specify):	Sufficient self-contained parking space for up to 5 vehicles				

4.	Conservation area	
	Is your property in a designated Conservation Area (that is an area of special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)?	[ ]YES [x]NO [ ]Don't know
5.	Listed buildings	
	Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)?	[ ]YES [x]NO
6.	Alterations/additions/extensions	
а	(i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?	[ ]YES [x]NO
	If you have answered yes, please describe below the changes which you have made:	
	(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?	[]YES[]NO
	If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.	
	If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:	
b	Have you had replacement windows, doors, patio doors or double glazing installed in your property	[x]YES [ ]NO
	If you have answered yes, please answer the three questions below:	
	(i) Were the replacements the same shape and type as the ones you replaced?	[x]YES [ ]NO
	(ii) Did this work involve any changes to the window or door openings?	[ ]YES [x]NO
	(iii) Please describe the changes made to the windows doors, or patio doors (with approximate dates when the work was completed):	
	Some double glazing units replaced, principally in conservatory - 2025	
	Please give any guarantees which you received for this work to your solicitor or estate agent.	
7.	Central heating	
а	Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property - the main living room, the bedroom(s), the hall and the bathroom).	[x]YES [ ]NO

	If you have answered yes or partial - what kind of central heating is there? (Examples: gas-fired, solid fuel, electric storage heating, gas warm air).	
	Ground source heat pump serving underfloor heating downstairs and radiators upstairs.	
	If you have answered yes, please answer the three questions below:	
	(i) When was your central heating system or partial central heating system installed?	
	2011 the ground source replaced gas central heating.	
	(ii) Do you have a maintenance contract for the central heating system?	[x]YES [ ]NO
	If you have answered yes, please give details of the company with which you have a maintenance contract	
	Nibe, for annual servicing only.	
	(iii) When was your maintenance agreement last renewed? (Please provide the month and year).	
	it is a rolling annual contract still in force.	
8.	Energy Performance Certificate	
	Does your property have an Energy Performance Certificate which is less than 10 years old?	[x]YES [ ]NO
9.	Issues that may have affected your property	
а	Has there been any storm, flood, fire or other structural damage to your property while you have owned it?	[x]YES [ ]NO
	If you have answered yes, is the damage the subject of any outstanding insurance claim?	[ ]YES [x]NO
b	Are you aware of the existence of asbestos in your property?	[ ]YES [x]NO
	The you aware of the existence of aspestos in your property!	[]Don't know
	If you have answered yes, please give details:	
10.	Services	

	Services	Connected	Supplie	er	
	Gas or liquid petroleum gas	Y	Flowga	as Britain Ltd	
	Water mains or private water supply	Y	Scottis	h Water	
	Electricity	Y	Octopus Energy		
	Mains drainage	N			
	Telephone	N			
	Cable TV or satellite	N			
	Broadband	Y	Starlin	k	
)	Is there a septic tank system at your property?		[x]YES [ ]NO		
	If you have answered yes, please answer the two questions below:				
	(i) Do you have appropriate consents for the discharge from your septic tank?		[x]YES [ ]NO		
			[]Don't know		
	(ii) Do you have a maintenance contract for your septic tank?		[x]YES [ ]NO		
	If you have answered yes, please give deta which you have a maintenance contract:	ils of the company v	with		
	Brig Environmental for annual service. The Biodisk BA to BC and was installed in 2024		eter		
11.	. Responsibilities for shared or common areas				
a	Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area?		anything	[ ]YES [x]NO	
	If you have answered yes, please give details:				
b	Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas?		[ ]YES [x]NO		
	If you have answered yes, please give details:			[ ]N/A	
C	Has there been any major repair or replacement of any part of the roof during the time you have owned the property?		[ ]YES [x]NO		
d	Do you have the right to walk over any of your neighbours' property- for example to put out your rubbish bin or to maintain your boundaries?		[ ]YES [x]NO		
	If you have answered yes, please give details:				

е	As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries?	[ ]YES [x]NO
	If you have answered yes, please give details:	
f	As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privatelyowned.)	[ ]YES [x]NO
	If you have answered yes, please give details:	
12.	Charges associated with your property	
а	Is there a factor or property manager for your property? If you have answered yes, please provide the name and address, and give details of any deposit held and approximate charges:	[ ]YES [x]NO
b		[ ]YES [x]NO
	Is there a common buildings insurance policy?	[]Don't know
	If you have answered yes, is the cost of the insurance included in your monthly/annual factors charges?	
С	Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, for example to a residents' association, or maintenance or stair fund.	
13.	Specialist works	
а	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?	[ ]YES [x]NO
	If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property.	
b	As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property?	[ ]YES [x]NO
	If you have answered yes, please give details:	
С	If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work?	[]YES[]NO
	If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself please write below who has these documents and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate. Guarantees are held by:	

14.	Guarantees		
а	Are there any guarantees or warranties for any of the following:		
(i)	Electrical work	[x]NO [ ]YES [ ]Don't know [ ]With title deeds [ ]Lost	
(ii)	Roofing	[x]NO [ ]YES [ ]Don't know [ ]With title deeds [ ]Lost	
(iii)	Central heating	[x]NO [ ]YES [ ]Don't know [ ]With title deeds [ ]Lost	
(iv)	National House Building Council(NHBC)	[x]NO [ ]YES [ ]Don't know [ ]With title deeds [ ]Lost	
(v)	Damp course	[x]NO [ ]YES [ ]Don't know [ ]With title deeds [ ]Lost	
(vi)	Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)	[x]NO [ ]YES [ ]Don't know [ ]With title deeds [ ]Lost	
b	If you have answered 'yes' or 'with title deeds', please give details of the work or installations to which the guarantee(s) relate(s):		
С	Are there any outstanding claims under any of the guarantees listed above?	[ ]YES [x]NO	
	If you have answered yes, please give details:		

15.	Boundaries		
	So far as you are aware, has any boundary of your property been	[ ]YES [x]NO	
	moved in the last 10 years?	[]Don't know	
	If you have answered yes, please give details:		
16.	Notices that affect your property		
In th	In the past three years have you ever received a notice:		
а	advising that the owner of a neighbouring property has made a planning application?	[ ]YES [x]NO	
b	that affects your property in some other way?	[ ]YES [x]NO	
С	that requires you to do any maintenance, repairs or improvements to your property?	[ ]YES [x]NO	
	If you have answered yes to any of a-c above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchaser of your property.		

Declaration by the seller(s)/or other authorised body or person(s) I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.		
Signature(s):	Peter James Peacock	
Capacity:	[x]Owner	
Capacity.	[ ]Legally Appointed Agent for Owner	
Date:	13/05/2025	